
CONJUNTO APOYA PIES CONDUCTOR



Rating: Not Rated Yet
Price:
Variant price modifier:

Base price with tax:

Price with discount:

Salesprice with discount:

Sales price:

Sales price without tax:

Discount:

Tax amount:

Ask a question about this product

Description

Ref.	Título	Código
1	PEDALIN APOYA PIE CONDUCTOR ARMADO	50-42300
2	BARRA APOYA PIES CONDUCTOR	50-42310
3	PATINES DE GOMA CONDUCTOR	50-42381
4	SOSTÉN LATERAL	50-42210
5	BULON I CON CABEZA	50-93121
6	TUERCA M10X1.25	50-GB/T6-13
7	RESORTE SOSTÉN LATERAL	50-42922
8	BULON M8X16	50-GB/T1-9
9	GUÍA PATINES DE GOMA	50-42315
10	BULON INTERIOR PATINES	50-93351